



**THIS IS THE PROBLEM!**

- 1) We did NOT accept two OK frames on 2nd CAN bus b/c of "not the same interface"
- 2) Start frame of the next transfer #2 "resynchronized" state machine for the 2nd interface & tid=2
- 3) Finally coming 2 frames (at tid=1) on the 1st CAN are "too late!" - we already looking for tid=2 and 2nd CAN interface.

